

TOTAL PETROCHEMICALS & REFINING USA, INC.

Port Arthur Refinery

FEDERAL EXPRESS

Chief
Environmental Enforcement Section
Environmental and Natural Resources Division
U.S. Department of Justice
P.O. Box 7611
Ben Franklin Station
Washington, D.C. 20044-7611
Reference Case No. 90-5-2-1-08283/3

RE: Force

Force Majeure Notification

Consent Decree Reference Case No. 90-5-2-1-08283/3

TOTAL Petrochemicals USA, Inc. Port Arthur Refinery, Port Arthur, Texas

September 11, 2017

To Whom It May Concern:

Pursuant to Part XVIII of the above-referenced Consent Decree, Total Petrochemicals & Refining USA, Inc. (Total) is notifying the EPA of a Force Majeure that has caused or may cause a delay or impediment to performance in compliance with provisions of the above-referenced Consent Decree.

The Force Majeure event was the passage of Hurricane Harvey through the Beaumont-Port Arthur area of southeast Texas and the resulting flooding throughout the area. Due to rainfall exceeding 47 inches in a period of 5 days, the Port Arthur Refinery experienced significant flooding. Beginning Monday, August 28, Refinery personnel were unable to travel to work due to impassable roads and flooding in their homes. On August 28 and 29, the Refinery was continuing limited operations with available personnel. Access to areas of the Refinery was limited due to flooding. On Wednesday, August 30, the electrical power supply to the Refinery terminated due to a failure at the Entergy Gulf States Substation when the relay system was damaged as a result of flooding. Loss of electric power resulted in a total shutdown of Refinery operations. At the time of this Force Majeure notification, the Refinery remains shut down. Refinery management and staff are working to bring equipment and processing units back on line.

As units are returned to service, there may be periods in which flaring occurs. The Refinery will implement start-up procedures to safely put units into operation and to minimize flaring and emissions from the Tailgas Thermal Oxidizers associated with the refinery's Sulfur Recovery Plants.

In compliance with the Force Majeure provisions of Part XVIII, please find attached to this notification a chart, in Excel format, listing the Consent Decree provisions for which there is or will be a delay or impediment to performance in compliance with provisions of the Consent Decree. The chart includes for each affected provision: cause(s) of the delay or impediment to performance; anticipated period of non-compliance or delay; measures taken or to be taken to minimize the period of non-compliance or delay; and the anticipated schedule or date by which those measures will be implemented.

Force Majeure Notification Consent Decree Reference Case No. 90-5-2-1-08283/3 TOTAL Petrochemicals USA, Inc. Port Arthur Refinery, Port Arthur, Texas September 11, 2017

I certify under penalty of law that I have personally examined and am familiar with the information submitted herein and that I have made a diligent inquiry of those individuals immediately responsible for obtaining the information and that to the best of my knowledge and belief, the information submitted herewith is true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment.

If you have any questions or comments, please contact Jannetta Ned, EPA Consent Decree Coordinator, at (409) 985-0268.

Sincerely,

Dorothy Bartol

Manager - HSSE – Port Arthur Refinery

Total Petrochemicals & Refining USA, Inc.

Force Majeure Notification Consent Decree Reference Case No. 90-5-2-1-08283/3 TOTAL Petrochemicals USA, Inc. Port Arthur Refinery, Port Arthur, Texas September 11, 2017

cc:

ELECTRONIC COPY

Chief Air, Toxics, and Inspections Coordination Branch U.S. Environmental Protection Agency, Region 6 1445 Ross Avenue Dallas, Texas 75202

Dorothy Bartol Manager - HSSE – Port Arthur Refinery Total Petrochemicals & Refining USA, Inc. P.O. Box 849 Port Arthur, Texas 77641-0849

Pat Y. Spillman, Jr. Senior Attorney, Legal Department Total Petrochemicals & Refining USA, Inc. P.O. Box 674411 Houston, Texas 77267-4411

CERTIFIED MAIL

Director, Air Enforcement Division Office of Civil Enforcement U.S. Environmental Protection Agency Mail Code 2242-A 1200 Pennsylvania, N.W. Washington, D.C. 20460-0001

FEDERAL EXPRESS

Director, Air Enforcement Division Office of Civil Enforcement C/O Matrix New World Engineering, Inc. 26 Columbia Turnpike Florham Park, New Jersey 07932

Electronic PDF copies to: csullivan@matrixnewworld.com; nfodzo.prince@epa.gov; <a href="mailto:nfodzo.pri



Section or Part	Paragraph#	Action Item (i.e. Description of Consent Decree Paragraph)	Cause(s) of Delay or Impediment to Performance	Anticipated Period of Non-compliance or Time Delay	Measures Taken or To Be Taken to Prevent or Minimize Period of Non- compliance or Delay	Schedule for Implementation of Measures
v	11	Limit NOx emissions from the FCCU to 30 ppmvd or less on a 365-day rolling average basis and 60 ppmvd or less on a 7-day rolling average basis.	Loss of electric power to the Refinery; exceedance of emission limit during the heat-up of the FCCU in preparation for a safe shutdown	The 7-day rolling average may be exceeded for up to 12 hours during FCCU warm up	Electric power restored to the refinery September 5, 2017; Working to warm unit up in preparation for a safe shutdown	Warming up of the FCCU anticipated for September 12 through 30, 2017
V	13	Limit SO2 emissions from the FCCU to 25 ppmvd or less on a 365-day rolling average basis and 50 ppmvd or less on a 7-day rolling average basis.	Loss of electric power to the Refinery; exceedance of emission limit during the heat-up of the FCCU in preparation for a safe shutdown	The 7-day rolling average may be exceeded for up to 12 hours during FCCU warm up	Electric power restored to the refinery September 5, 2017; Working to warm unit up in preparation for a safe shutdown	Warming up of the FCCU anticipated for September 12 through 30, 2017
v	15	Limit PM emissions from the FCCU to 0.5 pounds PM or less per 1000 pounds coke burned on a 3-hour average basis.	Loss of electric power to the Refinery; exceedance of emission limit during the heat-up of the FCCU in preparation for a safe shutdown	The 3-hour average may be exceeded for up to 12 hours during FCCU warm up	Electric power restored to the refinery September 5, 2017; Working to warm unit up in preparation for a safe shutdown	Warming up of the FCCU anticipated for September 12 through 30, 2017
v	15	Limit PM emissions from the FCCU to 0.5 pounds PM or less per 1000 pounds coke burned on a 3-hour average basis.	Loss of electric power to the Refinery; exceedance of emission limit during the heat-up of the FCCU in preparation for a safe shutdown	up to 12 hours during FCCU warm up	Electric power restored to the refinery September 5, 2017; Working to warm unit up in preparation for a safe shutdown	Warming up of the FCCU anticipated for September 12 through 30, 2017



Section or Part	Paragraph#	Action Item (i.e. Description of Consent Decree Paragraph)	Cause(s) of Delay or Impediment to Performance	Anticipated Period of Non-compliance or Time Delay	Measures Taken or To Be Taken to Prevent or Minimize Period of Non- compliance or Delay	Schedule for Implementation of Measures
V	16	Continuously monitor and record (1) the pressure drop across the wet gas scrubber, and (2) the scrubber liquid to gas ratio. Report as an emission exceedence, in accordance with the requirements of 40 C.F.R. Part 60, Subpart J, and of this Consent Decree, any three-hour period in which the average venturi pressure differential falls below the minimum value established through the most recent stack sampling performed on the FCCU wet gas scrubber stack pursuant to the procedures set forth in Texas Commission on Environmental Quality Permit Number 46396.	Loss of electric power to the Refinery; exceedance of emission limit during the heat-up of the FCCU in preparation for a safe shutdown	up to 12 hours during FCCU warm up	Electric power restored to the refinery September 5, 2017; Working to warm unit up in preparation for a safe shutdown	Warming up of the FCCU anticipated fo September 12 through 30, 2017
v	17	Limit CO emissions from the FCCU to 100 ppmvd or less on a 365-day rolling average basis and 500 ppmvd or less on a 1-hour average basis.	Loss of electric power to the Refinery; exceedance of emission limit during the heat-up of the FCCU in preparation for a safe shutdown	The 1-hour average may be exceeded for up to 12 hours during FCCU warm up	Electric power restored to the refinery September 5, 2017; Working to warm unit up in preparation for a safe shutdown	Warming up of the FCCU anticipated for September 12 through 30, 2017
V	27	Conduct a CGA on each CEMS installed on a Covered Heater or Boiler with a Heat Input Capacity > 100 MMBTU/hr	Loss of electric power to the Refinery - Unable to conduct CGAs	8 days	Expedite the performance of CGAs (Conduct two (2) CGAs per day)	October 9, 2017



Total Petrochemicals & Refining USA, Inc. Port Arthur Refinery

Consent Decree

Section or Part	Paragraph#	Action Item (i.e. Description of Consent Decree Paragraph)	Cause(s) of Delay or Impediment to Performance	Anticipated Period of Non-compliance or Time Delay	Measures Taken or To Be Taken to Prevent or Minimize Period of Non- compliance or Delay	Schedule for Implementation of Measures
V	29	For all heaters and boilers at the refinery, comply with applicable requirements of 40 CFR Part 60 Subparts A and J for fuel gas combustion devices.	exceedance of emission limit during re-	The 3-hour rolling average may be exceeded for up to 8 hours during re-start of heaters and boilers	Electric power restored to the refinery September 5, 2017; Working to return units to service	Re-start of all Refinery processing units anticipated by September 30, 2017
VI	32	For all Sulfur Recovery Plants (SRPs) at the refinery, comply with 40 CFR Part 60.104(a)(2), except during the Startup, Shutdown, or Malfunction of an SRP or the Malfunction of an associated TGU.	Loss of electric power to the Refinery; exceedance of emission limit during re- start	The 12-hour rolling average may be exceeded for up to 24 hours during restart of Sulfur Recovery Units	Electric power restored to the refinery September 5, 2017; Working to return units to service	Re-start of all Refinery processing units anticipated by September 30, 2017
VI	44.(ii) 55 56	Estimate the quantity of SO2 emitted and the calculations used to determine emissions; Flaring and Tail Gas Calculations	Loss of electric power to the Refinery; unable to monitor or record any flow and concentration data	The SO2 emissions associated with the loss of electric power at the refinery on August 30, 2017 will not be determined using the guidance provided in Paragraphs 55 and 56	The SO2 emissions associated with the loss of electric power at the refinery on August 30, 2017 will be determined using historical data and process knowledge	The SO2 emissions with be submitted with the Root Cause Failure Analysis by October 14, 2017
VII	66	Monitor for breakthrough between primary and secondary carbon canisters each Working Day.	Unable to conduct monitoring due to flooding of the plant and city of Port Arthur as a result of Hurricane Harvey; personnel unable to get to the refinery; unable to conduct monitoring due to a loss of power plant wide	Unable to monitor for carbon canister breakthrough for 6 days	Monitoring resumed on September 6, 2017	Monitoring resumed on September 6, 2017



Consent Decree

Section or Part	Paragraph#	Action Item (i.e. Description of Consent Decree Paragraph)	Cause(s) of Delay or Impediment to Performance	Anticipated Period of Non-compliance or Time Delay	Measures Taken or To Be Taken to Prevent or Minimize Period of Non- compliance or Delay	Schedule for Implementation of Measures
VII	90	individual drain systems.	Unable to complete all visual drain seal trap monthly inspection due to flooding of the plant and city of Port Arthur as a result of Hurricane Harvey unable to get to the refinery; Unable to complete monthly inspections due to a loss of power plant wide.	Unable to inspect the drain seal traps for 6 days	Inspections for September will be started as soon as units are returned to service, it is deemed safe to enter the units, and safe housing has been established for the LDAR Contractor	Monthly inspections for September to be completed by 9/30/2017
VII	90	Conduct weekly visual inspections of all conservation vents or indicators on process sewers for detectable leaks, reset any vents where leaks are detected, and record the results of such weekly inspections.	Unable to conduct weekly inspections due to flooding of the plant and city of Port Arthur as a result of Hurricane Harvey; personnel unable to get to the Refinery; unable to conduct weekly inspections due a loss of power plant wide	Unable to conduct weekly inspections of indications on process sewers for 1 week		Weekly inspections resumed on September 7, 2017
VIII	107	Monitor valves for leaks on a quarterly basis, or unless more frequent monitoring is required by a federal, state or local regulation.	Unable to complete monthly monitor of valves due to flooding of the plant and city of Port Arthur as a result of Hurricane Harvey; Unable to get to the refinery; Damage to the housing facility for LDAR Contractor occurred due to Hurricane Harvey	Unable to complete August monthly monitoring of LDAR components	Monitoring for September will be started as soon as units are returned to service, it is deemed safe to enter the units, and safe housing has been established for the LDAR Contractor	Monthly monitoring for September to be completed by 9/30/2017
VIII	108	Make first attempt at repair for leaking valves within 5 days	Unable to make first attempt at repair on valves within 5 days due to flooding of the plant and city of Port Arthur as a result of Hurricane Harvey; Unable to get to the refinery	within 5 days for one (1) component and we anticipate the delay to be 20 days	First attempts at repair of a component will be performed as soon as units are returned to service and it is deemed safe to work on equipment; and safe housing has been established for the LDAR Contractor	First attempt anticipated to be complete by 9/30/2017



Section or Part	Paragraph #	Action Item (i.e. Description of Consent Decree Paragraph)	Cause(s) of Delay or Impediment to Performance	Anticipated Period of Non-compliance or Time Delay	Measures Taken or To Be Taken to Prevent or Minimize Period of Non- compliance or Delay	Schedule for Implementation of Measures
УШ	108	Complete repair of leaking valves within 15 days	Unable to complete final repair of leaking valves within 15 days due to flooding of the plant and city of Port Arthur as a result of Hurricane Harvey unable to get to the refinery; Unable to complete monthly inspections due to a loss of power plant wide.	days for fifteen (15) component and we anticipate the delay to be 20 days	Repair of a component will be completed as soon as units are returned to service and it is deemed safe to work on equipment; and safe housing has been established for the LDAR Contractor	Repair attempt anticipated to be complete by 9/30/2017

Ser Angalok Akit (18		•
SENDER: COMPLETE THIS SECTION	COMPLETE THIS SECTION ON	DELIVERY
 Complete items 1, 2, and 3. Print your name and address on the reverse so that we can return the card to you. 	A. Signature	☐ Agent ☐ Addresses
 Attach this card to the back of the mailpiece, or on the front if space permits. 	B. Received by (Printed Name)	C. Date of Delivery
Director, Air Enforcement Division Office of Civil Enforcement	D. Is delivery address different fro if YES, enter delivery address	
U.S. Environmental Protection Agency Mail Code 2242-A 1200 Pennsylvania, N.W. Washington, D.C. 20460-001		
Mail Code 2242-A 1200 Pennsylvania, N.W.	3. Service Type Adult Signature Adult Signature Restricted Delivery Certified Mail® Certified Mail Restricted Delivery Certified Polivery	Delivery Return Receipt for
Mail Code 2242-A 1200 Pennsylvania, N.W. Washington, D.C. 20460-001	☐ Adult Signature ☐ Adult Signature ☐ Certified Mail®	☐ Registered Mail Restricte ☐ Registered Mail Restricte Delivery

•

SHIP DATE: 11SEP17 ACTWGT: 0.50 LB CAD: 2872926/INET3920

PORT ARTHUR, TX 77642 UNITED STATES US

BILL SENDER

DIRECTOR, AIR ENFORCEMENT OFFICE MATRIX NEW WORLD ENGINEERING, INC. 26 COLUMBIA TURNPIKE

549J1/FF19/104C

FLORHAM PARK NJ 07932 (973) 240-1800 REF: JANNETT. INV:

REF: JANNETTA BOWDEN-NED

PO:

DEPT: 8014065





TUE - 12 SEP 10:30A **PRIORITY OVERNIGHT**

7702 2907 5410

07932 **EWR**





- 1. Use the 'Print' button on this page to print your label to your laser or inkjet printer.
 2. Fold the printed page along the horizontal line.
 3. Place label in shinning named.
- Place label in shipping pouch and affix it to your shipment so that the barcode portion of the label can be read and scanned.

Warning: Use only the printed original label for shipping. Using a photocopy of this label for shipping purposes is fraudulent and could

result in additional billing charges, along with the cancellation of your FedEx account number.

Use of this system consitiutes your agreement to the service conditions in the current FedEx Service Guide, available on fedex.com. FedEx will not be responsible for any claim in excess of \$100 per package, whether the result of loss, damage, delay, non-delivery, misdelivery, or misinformation, unless you declare a higher value, pay an additional charge, document your actual loss and file a timely claim. Limitations found in the current FedEx Service Guide apply. Your right to recover from FedEx for any loss, including intrinsic value of the package, loss of sales, income interest, profit, attorney's fees, costs, and other forms of damage whether direct, incidental, consequential, or special is limited to the greater of \$100 or the authorized declared value. Recovery cannot exceed actual documented loss. Maximum for items of extraordinary value is \$1,000, e.g. jewelry, precious metals, negotiable instruments and other items listed in our ServiceGuide. Written claims must be filed within strict time limits, see current FedEx Service Guide.

ORIGIN ID:OZAA (409) 985-0680 JANNETTA BOWDEN-NED TOTAL PETROCHEMICALS USA, INC. HWY 366 & 32ND ST

SHIP DATE: 11SEP17 ACTWGT: 0.50 LB CAD: 2872926/INET3920

PORT ARTHUR, TX 77642 UNITED STATES US

BILL SENDER

CHIEF, ENVIROMENTAL ENFORCEMENT SEC U.S. DEPT. OF JUSTICE 601 D ST NW 2121

549.11/FF19/104C

WASHINGTON DC 20579 (202) 514-2000 RFF- 14-2000

REF: JANNETTA BOWDEN-NED

DEPT: 8014065





TUE - 12 SEP 10:30A **PRIORITY OVERNIGHT**

7702 2906 5328

20579 IAD



After printing this label:

Use the 'Print' button on this page to print your label to your laser or inkjet printer.
 Fold the printed page along the horizontal line.
 Place label in shipping pouch and affix it to your shipment so that the barcode portion of the label can be read and scanned.

Warning: Use only the printed original label for shipping. Using a photocopy of this label for shipping purposes is fraudulent and could

result in additional billing charges, along with the cancellation of your FedEx account number.

Use of this system constitutes your agreement to the service conditions in the current FedEx Service Guide, available on fedex.com. FedEx will not be responsible for any claim in excess of \$100 per package, whether the result of loss, damage, delay, non-delivery, mischelivery, or misinformation, unless you declare a higher value, pay an additional charge, document your actual loss and file a timely claim. Limitations found in the current FedEx Service Guide apply. Your right to recover from FedEx for any loss, including intrinsic

value of the package, loss of sales, income interest, profit, attorney's fees, costs, and other forms of damage whether direct, incidental, consequential, or special is limited to the greater of \$100 or the authorized declared value. Recovery cannot exceed actual documented loss.Maximum for items of extraordinary value is \$1,000, e.g. jewelry, precious metals, negotiable instruments and other items listed in our ServiceGuide. Written claims must be filed within strict time limits, see current FedEx Service Guide.